

Sorry on what sounds only personal worries which I heard or saw on screen yesterday ,there are 4 points concerning us regards driveway to our property home and equestrian centre also changes to bridle ways and footpaths also effects of bund 7 & 8 on our land & trees

1 when you say bridle way to be diverted to install conveyor this would have to be drive way to support large horse boxes ,tractor with long trailer delivering hay or straw dustbin wagon

We cannot be diverted to north Cookley entrance as none of vehicles mentioned above would have enough room to turn 90 degrees into our tight entrance approximately 11 feet , but have no problem coming straight on up present

2 bridle way mentioned as figure of 8 is this an assumption as it means changing foot path to bridle way. This was suggested by NRS representative at last inquiry but was told unlikely to be allowed.

3 Also mentioned was permitted bridle way on East side of phase 5/4 which I take as not permanent and can be removed by someone ie land owner.

4 Bund 7 when seen on screen touching our paddock at northern end which has a beautiful Cedar tree approx 3 metres from bund so wonder if bund closeness ,weight of bund and excavation beyond has been considered for health now and future

The same applies to bund 8 Northern side phase 1 which comes close to our woodland which has many types of trees including mature oak trees that abuts north side phase 1, same concerns as Cedar tree.

I did speak to person doing tree survey 20th May 2019 access 2 trees (photo taken) he did not enter our land as trees was not on site of quarry .

Andrew McDonald The bungalow Lea Castle Equestrian Centre