



Lea Castle Farm



SECTION A-A': West to East Section through Tree 22



SECTION B-B': North to South Section through Tree 22


T22 - Sweet Chestnut *Castanea sativa*

HEIGHT (m)	STEMS No / Diameter (mm)	STRUCTURAL CONDITION	SURVEY COMMENT
9	1 / 1200	C: Poor S: Poor B: Poor	Tree has apical dieback, stags horns and damaged bark at base.

C: Crown S: Stem B: Basal Area

Note: the tree currently stands isolated within the existing field

Typical Sections through land around Tree 22



Location of Sections (1:5,000 @A4)



PROJECT:

Lea Castle Farm

TITLE:

Typical Sections through land around Tree 22

REF NO:

KD.LCF.041

DATE:

April 2021

SCALE:

1:500 @ A4

STATUS:

FINAL



This drawing may not be used without the consent of Kedd Development Limited
Fox Studio, Much Wenlock, Shropshire TF13 6BL
© Crown copyright and database rights [2017] Ordnance Survey 0100031673